



**National
Aeronautical
Laboratory**

Documentation Sheet

Document Classification
Restricted

Title : Failure of Connecting Rod
Bolts of a Prototype Engine

Document No.

PD MT 8646

Date of issue: Aug '86

Author(s) : S.Radhakrishnan, R.V.Krishnan, .
M.A.Venkataswamy and
V.Ramachandran

Contents 7 pages

Division : Materials Science

No. of copies: 16

*External
participation* :

NAL Project No.
MT-9-861

Sponsor :

Sponsor's Project No.

Approval : V.Ramachandran

Remarks :

Keywords : Engine, Connecting rod, EN 24 steel,
Maraging Steel

Abstract :

The report describes the analysis of failures
of connecting rods of a prototype engine.
These were made of EN 24 and Maraging steels.